FIRE ALARM SYSTEM INSPECTION REPORT



P.O. Box 326326 Hagatna, GU 96932 Office: (671) 648-FIRE (3473) Email: sales@falconfireguam.com CLB 08-0377 C19 & C20

TYPE OF INSPECTION	N	SYSTEM SPECIFICATION	IS	
NEW INSTALL		Manufacturer: Silent Knig		
ANNUAL		Model:	IFP-2000ECS	
SEMI-ANNUAL X		Addressable		X
OTHER		Conventional Other		
	N 100 101 01 000 1			
Area Inspected			YES	NO
ALL		U.L. Approved	X	

		9/16/2022	
TECHNICIAN'S NAME	Eloy Santos	W.O.#	
JOB NAME	Guam Community College		
PHYSICAL ADDRESS	1 Sesame St. Mangilao, GU 96913		

COMPANY INFORM	ATION					
Name:	Guam Community College					
Contact:	Huan Hosei					
Address:	P.O. Box 23069 GMF Barrigada, GU 96921					
Emall:	materialsma	materialsmanagement@guamcc.edu				
Office#:	671-735-5540/2	Mobile#:				

Device Smoke Detectors Duct Detectors	Photoelectric	lonization	Other	Visual				M FOR VALUE AND ADDRESS OF THE PROPERTY OF THE
				Vioudi	Functional	Satisfactory	Unsatisfactory	NOTES
Duct Detectors				X	X		X	See Discrepancies
	Conventional	Addressable						
Manual Pull Stations	-	X		X	X	×		
	Rate of Rise	Fixed						
Heat Detectors		X		X	X	×		
	Pressure	Paddle						
Water-flow Switches		X		X	X	3		Not Tested
	Tamper	Hood			Hessain in the			
Other Switches	X			X	X	X		
	Satisfactory	Unsatisfactory				Menal	Eventional	NOTES
	Calleracia	Onoutonactory				Visuai	runctional	See discrepancies
				SECURIO DE LA COLONIA DE LA CO	173			See discrepancies
iei X				Horn/Strbs				
		X		Strobes	264			Speaker/Strobes
/ Functions				N/A	Not Tested	Satisfactory	Unsatisfactory	NOTES
						X		#**#**********************************
ver							~	See Discrepancies
						\sim		Gee Discrepancies
						\rightarrow		
						X		
al						×		
t						X		Ground Faults Active
Switches						X		
unning					V			
				$\overline{}$				
itions				NVA	Not Tostad	Catlefantoni	. Hannettafantanı	NOTES
					NOL TESTEU	V	Olisatisfactory	NOTES
						\/		See Discrepancies
						X		
						X		
witch						X		
Ds						X		
				X		•		
nctions				N/A	Not Tested	Satisfactory	Unsatisfactory	Edituridation establisher NOTES (species) (Established)
e						X		
oture						X		
			Carrier Commission (1988)	X				
				$\overline{}$				
00				\rightarrow				
					X			
nciators							X	See discrepancies
ES FOUND		DECOMPLEMENT A	TIONS & COTT	MENTS		400-	WED FOR INS	
				mEN13		APPRO	VED FOR 155U	E BY CERTIFICATION STATUS
Location	Options S	See discrepancy lis	ı			M		
						///		9/20/2022 CERTIFIE
t t t t t t t t t t t t t t t t t t t	Other Switches Communication System N/A Not Tested Ones Signature Functions Ver Function	Water-flow Switches Tamper Other Switches Communication System N/A Not Tested Satisfactory ones Punctions Ver Ince Switch bile al al al al bilitions uits tis e Switch Switch witch EDs Inctions Inctio	Water-flow Switches Tamper Other Switches Communication System N/A Not Tested Satisfactory Unsatisfactory ones S S S S S S S S S S S S S S S S S S S	Water-flow Switches Tamper	Water-flow Switches Tamper Hood	Water-flow Switches Tamper Hood	Water-flow Switches Tamper Other Switches Communication System Signaling Devices Device Quantity Visual Speakers 175 Homs Hom/Stribs Strobes 264 Functions N/A Not Tested Satisfactory	Water-flow Switches Tamper Hood





November 8, 2022

Guam Community College 1 Sesame Street Mangilao, GU 96913 Tel: (671) 735-5540/2

Re: Fire Alarm System Repairs

Provided for your review is our proposal to perform the fire alarm repairs for Guam Community College.

FIRE ALARM REPAIRS:

Inclusions:

- 1. All labor and materials to troubleshoot Active Supervisory AHC Sprinkler Valve Trouble Z250 M06 P043. Time and material basis.
- 2. All labor and materials to troubleshoot Active Supervisory Admin North Sprinkler Tamper Z001 M97 P001. Time and material basis.
- 3. All labor and materials to troubleshoot open circuit Admin South Sprinkler Waterflow (Monitor Open Circuit) Z12 M97 P015. Time and material basis.
- 4. All labor and materials to troubleshoot amplifier Circuit 2 Building 900 Speakers 02 (Amp CKT 2 Open Circuit) G016 M16, P002. Time and material basis.
- 5. All labor and materials to troubleshoot and replace speaker/speaker strobe devices if needed at Buildings A, C, D, 600, 900 and 5000. Time and material basis.
- 6. All labor and materials to troubleshoot and replace strobe/speaker strobe device if needed at Building 900. Time and material basis.
- 7. All labor to troubleshoot Building A M06 CKT 6. Time and material basis.
- 8. All labor and materials to troubleshoot smoke detector at Building 900. Time and Material basis.
- 9. All labor and materials to supply and replace a relay module LRC 2F Mech. Room A/C Shutdown (SLC Relay missing) G98 M10 P022.
- 10. All labor and materials to supply and replace pull station at FB Café Main Entry (Manual Pull Missing) Z6 M14 P005.
- 11. All labor and materials to supply and replace surge protector on RPS-1000 at Building 900.
- 12. All labor and materials to supply and replace One (1) heat detector in Building A 1F elevator landing.

Our price for this proposal is

Line Items 1-8 - \$110.00 per hour, per man, with labor to be performed during normal working hours. Materials to be assessed. Invoice is subject to change.

Line Item 8 - \$315.00 to replace smoke detector if needed.

Line Item 9 - \$280.00.

Line Item 10 - \$310.00.

Line Item 11 - \$398.00.

Line Item 12 - \$245.00.

NOTES:

- 1. Active Supervisory MPA Pump Room Sprinkler Controller Z250 M02 P029 GCC to fix Fire Pump controller first.
- 2. Per GCC's request, to be connected back after troubles have cleared:
 - RA-2000 01 MPA SBUS Communication Trouble M01 Building 300
 - RA-2000 20 SC SBUS Communication Trouble M20 Building 5000
 - RA-2000 08 LC SBUS Communication Trouble M08 Building 4000